

SITE IDENTIFICATION FORM

Initial I.D. (Y/N): N Follow-up Investigation (Y/N): Y

SITE INFORMATION (ID#20)

Site Name: VENTURA 1939

AKA:

SWIS #:56-CR-0019 County: Ventura Parcel #(s): Unknown

Location: HWY 33/101 Land Owner(s): Unknown

Address: Unknown

City: Unknown State: CA Zip: Ukn Phone: Ukn

Types of Waste: Unknown

Site Type: Closed Refuse Disposal Site

Disposal Area (Acre): Unknown SWFP Date: N/A WDR Number: N/A

Dates of Operations: Closed 1939 Closure Approved By: N/A

Land Use on or Within 1000 ft; 1 mile of boundary: Unknown

OBSERVATIONS

Date of Field Visit: N/A Sig. Change Since Last Visit? (Y/N/NA):N/A Surface Condition: N/A
Landfill Gas: N/A

Leachate: N/A

Other:

EXPLANATION

This site has not been located. The site was initially identified in the 1975 V.C. CoSWMP. The extent of identification was a dot on a map. See attached summary for documentation on location research.

RECOMMENDATION

Emergency Response: N/A Other: If location is identified an updated SIF will be completed

Reassess Site? (Y/N/NA): N/A No Further Action? (D Priority Y/N): Insufficient information is presently available to allow for the location of this site. It is recommended that the site be archived until additional information becomes available for the location of this site. Eliminate this site from the required inspection frequency.

Priority for Site Assessment (High/Med/Low): N/A

Prepared By: Barry Marczuk -LEA Date: 8/16/95 CIWMB Approval: C&R Branch 2/7/96